Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mesa IV 1/4 Mine AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I	Site Identification, Location and Status			
Site Names and ID numbers as applicable				
Mine ID:	415			
Map ID:	N223			
CERCLIS:	NNN000908882			
Navajo Abandoned Mine Land Reclamation Program: None				
Local name / Aliases: Mesa #4 1/4 Mine				
Chapter and local area: Cove Chapter				
County: Apa	ache State: Arizona			
Lat/Long: 36.5282303341 N / -109.261154141 W				
Nearby road	and highway: Indian Route 63 Local Post Office: Cove, AZ			
Surface Land Status: check one or more and provide ownership and contact information below				
Tribal Trust I Private Bureau of La State	Tribal Fee Land			
Subsurface Mineral Rights:				
No information on subsurface mineral rights ownership was found in the EPA/AUM Database.				
Claim and operator information:				
The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Vanadium Corp. of America from 1965 to 1968. No other historical ownership / lease information was identified in the EPA/AUM database.				
Number of residential structures within 200 feet of mine:				
None				
Estimated volume of mine waste onsite:				
None				

Part II Summary of radiological readings

Highest gamma radiation measurement:

411,359 counts per minute (cpm)

Describe any other radiological measurements:

A total of 1,776 gamma radiation measurements were collected from the mine site, ranging from 8,559 cpm to 411,359 cpm. Measurements in the vicinity of the waste debris were found at levels in up to 120,000 cpm. The measurements are represented in Figures 1 and 2.

Background Locations

Average background = 13,629 cpm


#1 10,889 cpm

#2 15,600 cpm

#3 14,400 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1789

 Minimum:
 0,00000

 Maximum:
 411359,00000

 Sum:
 43264123,00000

 Mean:
 24183,41140

 Median:
 12635,00000

 Standard Deviation:
 37485,79929

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: No Waste Pile onsite: Unknown

NAMLRP Project Number: None

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

of any reclamation caps. Note condition of all caps.				
Observed reclamation work and status:				
Adits				
None				
Waste Piles None				
Pits				
None				
Shafts				

Other Debris and Mine Features

None

None

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Mesa IV ¼ Mine consists of an area of 24,469.8 m². The mine was identified as being operational from 1965 to 1968. Historical documents showed the operator of the mine as Vanadium Corp. of America from 1965 to 1968. While operational, the mine had a total reported production volume of 344 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Mesa IV ¼ Mine **Chapter:** Cove

Decision Criteria

Is there an unreclaimed waste pile at the site? None

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? None

Is the cap/seal functionally intact? None

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

None

Part VI Photos



Photo 1. Mine site



Photo 2. Mine site



Photo 3. Mine site




Photo 4. Mine site

Part VII Contacts Reports and Information

Name:	<u>Stanley Edison</u> (928) 871-6861				
	Eugene Esplain (928) 871-7331				
Title or of	fficial role (if any) Navajo EPA Superfund Program				
Address_	PO Box 2946, Window Rock, AZ 86515				
Information provided <u>Lead Regulatory Agency</u>					
Name					
Title or official role (if any)					
Address					
Telephone	Telephone number				
Information provided					
Name					
Title or official role (if any)					
Telephone number					
Information provided					
Name					
Title or of	_				
Telephone					
Information	on provided				

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Mesa IV 1/4 Mine (415)
Cove Chapter, Navajo Nation, Arizona






Figure 2 - Gamma Radiation Measurements Mesa IV 1/4 Mine (415) Cove Chapter, Navajo Nation, Arizona



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- **15,000 20,000**
- **2**0,000 50,000
- 50,000 100,000
- > 100,000





Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 13,629 cpm

